Unit Job History

MnDOT

Report Printed: 12/03/2020 15:02:53 By User: BORC1ERI

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: 216068 - 2016 FORD F150										
WO Open Date: 2016-10-04 -										
10/04/2016 09:30:00	38	0	276435270	90-00	In-Service Entire Unit	10/04/2016 15:30:00	OCS000	1	DON	316.14
						WO Open Date: 2016-10-04		Count 1:		316.14
WO Open Date: 2017-05-26 -										
05/26/2017 00:00:00	4,304	0	276460913	PM-PM-PMA	PM "A" Service (Oil Change)	05/30/2017 08:59:58	1DU000	P	DON	85.47
						WO Open Date: 2017-05-26		Count 1:		85.47
WO Open Date: 2017-07-17 -										
07/17/2017 00:00:00	8,679	0	276465286	PM-PM-PMA	PM "A" Service (Oil Change)	07/19/2017 14:09:34	1DU000	P	DON	85.47
						WO Open Date: 2017-07-17		Count 1:		85.47
WO Open Date: 2017-09-26 -										
09/26/2017 00:00:00	14,833	0	276472214	PM-PM-PMA	PM "A" Service (Oil Change)	09/28/2017 13:04:54	1DU000	P	DON	85.47
						WO Open Date: 2017-09-26		Count 1:		85.47
WO Open Date: 2018-05-31 -										
05/31/2018 07:15:00	18,844	0	276501052	PM-PM-PMA	PM "A" Service (Oil Change)	05/31/2018 12:00:00	1DU000	P	DON	85.47
						WO Open Date: 2018-05-31		Count 1:		85.47
WO Open Date: 2018-08-10 -										
08/10/2018 00:00:00	23,553	0	276506979	PM-PM-PMA	PM "A" Service (Oil Change)	08/13/2018 07:53:04	1DU000	P	DON	85.47
						WO Open Date: 2018-08-10		Count 1:		85.47
WO Open Date: 2019-05-22 -										
05/22/2019 12:31:59	26,592	0	276536943	32-32-001	DO NOT USE Battery & Cables	05/22/2019 14:06:09	1DU000	N	DON	386.97
						WO Open Date: 2019-05-22		Count 1:		386.97
WO Open Date: 2020-07-22 -										
07/22/2020 07:44:04	31,205	0	276576913	22-93-002	Install GPS Module	07/22/2020 08:57:46	1DU000	M	DON	81.88
						WO Open Date: 2020-07-22		Count 1:		81.88
WO Open Date: 2020-11-16 -										
11/16/2020 07:37:09	31,702	0	276588070	34-02	Remove Body & Components	11/18/2020 07:45:00	1DU000	2	DON	70.95

Unit No: 216068 - 2016 FORD F150

WO Open Date: 2020-11-16 -

11/16/2020 07:37:09	31,702	0	276588070	34-93-002	Remove GPS Module	11/20/2020 10:07:58	1DU000	O	DON	0.00

WO Open Date: 2020-11-16 Count 2: 70.95

Unit No: 216068 **Count: 10** **1,283.29**

Total Job Count and Repair Cost: **Count**: **10** **1,283.29**

Unit Job History

Report Title: UNITJOBHISTDISP - Unit Job History V17.0
Report Author: FleetFocus M5
File Path: C:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\T79
Data Extracted: Thu Dec 03 2020 15:02:53 **Report User:** BORC1ERI
TZ: Central Standard Time
DLL Version: 2018.08.01
Report Comments: 5/31/06 - Focus No 7069 6/14/06 - Focus No 7996 & No 3053 7/12/06 - Focus No. 5392 03/28/07 - Focu 13916 07/02/07 - Focus No. 15696 10/08/07 - Focus No. 16414 02/08/08 - Focus No. 18696 01/21/09 - 22842 12/10/09 - Focus No. 24193 07/06/09 - Focus No. 25012 08/15/10 - Focus No. 31840 06/23/11 - 28649 09/06/11 - Focus No. 36445 11/11/11 - Focus No. 35887 06/04/12- Focus No. 39905 07/03/12 - F 39906 08/06/15 - FMV-3791
08/24/15 - FMV-3590 09/21/15 - FMV-4217 04/10/17 - FMV-9446

Parameters and Selection Filters

First Grouping: NONE
Second Grouping: OPEN_DT
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: {view_unit_wo.unit_no} = '216068' //Q=