Unit Job History

MnDOT

Report Printed: 09/23/2021 13:50:07 By User: BORC1ERI

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: 201350 - 2001 DIAMOND DRF102C										
WO Open Date: 2005-03-21 -										
03/21/2005 10:19:11	0	0	217101	PM-PM-PMI	PM Preventive Maintenance Inspection	03/21/2005 10:38:34	1DU000	P	DON	18.98
						WO Open Date: 2005-03-21			Count 1:	18.98
WO Open Date: 2005-08-10 -										
08/10/2005 10:30:00	0	0	9371548	32-66	DO NOT USE Mower Equipment	08/10/2005 10:30:58	1DU246	O	DON	414.14
						WO Open Date: 2005-08-10			Count 1:	414.14
WO Open Date: 2005-12-13 -										
12/13/2005 11:08:41	0	0	9388378	38-00	Repair/Repla Entire Unit	12/15/2005 11:55:18	1DU000	F	DON	55.22
12/13/2005 11:08:41	0	0	9388378	PM-PM-PMI	PM Preventive Maintenance Inspection	12/15/2005 10:49:11	1DU000	P	DON	57.10
12/13/2005 11:08:41	0	0	9388378	PM-PM-PML	PM Lubricate Chassis & Components	12/15/2005 11:00:02	1DU000	P	DON	10.84
						WO Open Date: 2005-12-13			Count 3:	123.16
WO Open Date: 2006-06-27 -										
06/27/2006 00:00:00	0	0	9416373	32-56-001	DO NOT USE Power Take Off	07/06/2006 00:00:00	1DU298	F	DON	209.83
06/27/2006 00:00:00	0	0	9416373	34-56-005	Remove POWER SHAFT ASSEMBLY- I	07/06/2006 00:00:00	1DU298	O	DON	433.44
						WO Open Date: 2006-06-27			Count 2:	643.27
WO Open Date: 2006-12-11 -										
12/11/2006 11:34:18	0	0	9435793	32-66	DO NOT USE Mower Equipment	12/12/2006 12:52:44	1DU000	F	DON	87.06
12/11/2006 11:34:18	0	0	9435793	PM-PM-PMI	PM Preventive Maintenance Inspection	12/12/2006 11:13:11	1DU000	I	DON	68.04
						WO Open Date: 2006-12-11			Count 2:	155.10
WO Open Date: 2007-06-18 -										
06/18/2007 07:40:49	0	0	9460316	56-00	Weld/Fabric Entire Unit	06/19/2007 07:46:27	1DU246	O	DON	179.85
06/18/2007 07:40:49	0	0	9460316	61-00	Travel Time Entire Unit	06/19/2007 07:46:27	1DU246	O	DON	149.88
						WO Open Date: 2007-06-18			Count 2:	329.73
WO Open Date: 2007-07-11 -										
07/11/2007 07:40:25	0	0	276072645	32-56-005	DO NOT USE POWER SHAFT ASSEMI	07/12/2007 14:27:05	1DU256	O	DON	418.68
						WO Open Date: 2007-07-11			Count 1:	418.68
WO Open Date: 2008-06-23 -										

Unit Job History

MnDOT

Report Printed: 09/23/2021 13:50:07 By User: BORC1ERI

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: 201350 - 2001 DIAMOND DRF102C										
WO Open Date: 2008-06-23 -										
06/23/2008 09:54:18	0	0	276113726	34-55	Remove Cargo Handling & Restraints	06/23/2008 11:57:52	1DU000	F	DON	59.33
06/23/2008 09:54:18	0	0	276113726	38-55	Repair/Repla Cargo Handling & Restraint	06/23/2008 16:59:50	1DU000	F	DON	265.69
06/23/2008 09:54:18	0	0	276113726	47-00	Inspect Entire Unit	06/23/2008 10:58:29	1DU000	O	DON	57.72
06/23/2008 09:54:18	0	0	276113726	56-55	Weld/Fabric Cargo Handling & Restraints	06/30/2008 10:24:51	1DU000	F	DON	216.92
						WO Open Date: 2008-06-23		Count 4:		599.66
WO Open Date: 2008-08-28 -										
08/28/2008 10:56:49	0	0	276120515	32-66-006	DO NOT USE Bearing/Pulley	09/08/2008 14:53:17	1DU298	F	DON	532.43
08/28/2008 10:56:49	0	0	276120515	38-66-007	Repair/Repla Mower Drive Belt	09/08/2008 15:19:51	1DU298	O	DON	213.16
08/28/2008 10:56:49	0	0	276120515	38-96	Repair/Repla Miscellaneous	09/08/2008 15:19:51	1DU298	F	DON	150.87
08/28/2008 10:56:49	0	0	276120515	61-00	Travel Time Entire Unit	09/08/2008 15:19:18	1DU298	F	DON	207.97
						WO Open Date: 2008-08-28		Count 4:		1,104.43
WO Open Date: 2008-10-16 -										
10/16/2008 12:33:24	0	0	276125569	56-66-001	Weld/Fabric Mower Deck	10/27/2008 11:41:33	1DU000	F	DON	92.35
10/16/2008 12:33:24	0	0	276125569	PM-PM-PMI	PM Preventive Maintenance Inspection	10/27/2008 11:41:33	1DU000	P	DON	0.00
						WO Open Date: 2008-10-16		Count 2:		92.35
WO Open Date: 2009-09-29 -										
09/29/2009 10:59:29	0	0	276165120	32-B1-260	DO NOT USE Drive Belt	10/01/2009 07:53:05	1DU000	O	DON	180.90
09/29/2009 10:59:29	0	0	276165120	32-B1-299	DO NOT USE Tensioner and All Pulleys	09/30/2009 15:13:38	1DU000	P	DON	337.54
09/29/2009 10:59:29	0	0	276165120	38-24-002	Repair/Repla PROPELLER SHAFT, BEI	10/05/2009 10:17:34	1DU000	O	DON	367.44
09/29/2009 10:59:29	0	0	276165120	56-66-001	Weld/Fabric Mower Deck	10/01/2009 15:14:14	1DU000	P	DON	329.00
09/29/2009 10:59:29	0	0	276165120	PM-PM-PMI	PM Preventive Maintenance Inspection	09/29/2009 14:15:11	1DU000	P	DON	92.13
						WO Open Date: 2009-09-29		Count 5:		1,307.01
WO Open Date: 2011-08-12 -										
08/12/2011 06:30:56	0	0	276237526	38-66-006	Repair/Repla Bearing/Pulley	08/19/2011 09:59:14	1DU000	O	DON	265.56
08/12/2011 06:30:56	0	0	276237526	61-00	Travel Time Entire Unit	08/19/2011 09:59:14	1DU000	F	DON	31.61
						WO Open Date: 2011-08-12		Count 2:		297.17

Unit Job History

MnDOT

Report Printed: 09/23/2021 13:50:07 By User: BORC1ERI

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: 201350 - 2001 DIAMOND DRF102C										
WO Open Date: 2011-09-22 -										
09/22/2011 06:29:10	0	0	276240840	32-66-007	DO NOT USE Mower Drive Belt	10/03/2011 16:00:43	1DU246	O	DON	247.72
						WO Open Date: 2011-09-22		Count 1:		247.72
WO Open Date: 2012-02-23 -										
02/23/2012 08:11:41	0	0	276257035	38-B1-260	Repair/Repla Drive Belt	03/13/2012 07:53:42	1DU000	F	DON	391.67
02/23/2012 08:11:41	0	0	276257035	PM-PM-PMI	PM Preventive Maintenance Inspection	02/23/2012 11:46:26	1DU000	I	DON	58.49
						WO Open Date: 2012-02-23		Count 2:		450.16
WO Open Date: 2013-06-25 -										
06/25/2013 06:00:07	0	0	276308504	32-66-006	DO NOT USE Bearing/Pulley	09/12/2013 10:12:34	1DU000	O	DON	730.56
						WO Open Date: 2013-06-25		Count 1:		730.56
WO Open Date: 2014-06-04 -										
06/04/2014 06:59:34	0	0	276347978	38-66-004	Repair/Repla Gearbox	06/04/2014 16:10:00	1DU298	O	DON	439.59
06/04/2014 06:59:34	0	0	276347978	61-00	Travel Time Entire Unit	06/04/2014 16:10:00	1DU298	F	DON	43.11
						WO Open Date: 2014-06-04		Count 2:		482.70
WO Open Date: 2014-06-18 -										
06/18/2014 10:55:45	0	0	276349180	22-66-001	Install Mower Deck	06/18/2014 15:28:35	1DU000	O	DON	165.11
						WO Open Date: 2014-06-18		Count 1:		165.11
WO Open Date: 2015-07-15 -										
07/15/2015 08:52:44	0	0	276390277	32-24	DO NOT USE Drive Shafts	08/03/2015 07:27:09	1DU298	B	DON	547.56
						WO Open Date: 2015-07-15		Count 1:		547.56
WO Open Date: 2017-06-27 -										
06/27/2017 12:46:08	0	0	276463329	32-66-006	DO NOT USE Bearing/Pulley	07/11/2017 16:04:37	1DU298	B	DON	676.40
						WO Open Date: 2017-06-27		Count 1:		676.40
WO Open Date: 2017-07-18 -										
07/18/2017 08:33:16	0	0	276465051	32-66-004	DO NOT USE Gearbox	08/09/2017 14:28:52	1DU298	B	DON	2,263.05
07/18/2017 08:33:16	0	0	276465051	32-66-007	DO NOT USE Mower Drive Belt	08/09/2017 14:28:52	1DU298	F	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: 201350 - 2001 DIAMOND DRF102C										
						WO Open Date: 2017-07-18			Count 2:	2,263.05
WO Open Date: 2017-08-09 -										
08/09/2017 14:30:20	0	0	276467212	32-66-006	DO NOT USE Bearing/Pulley	08/28/2017 07:33:53	1DU298	B	DON	538.46
						WO Open Date: 2017-08-09			Count 1:	538.46
WO Open Date: 2018-05-29 -										
05/29/2018 09:02:28	0	0	276500410	38-00	Repair/Repla Entire Unit	05/29/2018 11:58:49	1DU000	O	DON	224.04
						WO Open Date: 2018-05-29			Count 1:	224.04
WO Open Date: 2019-05-14 -										
05/14/2019 13:39:34	0	0	276536167	32-66-004	DO NOT USE Gearbox	07/16/2019 15:04:26	1DU298	O	DON	99.46
						WO Open Date: 2019-05-14			Count 1:	99.46
WO Open Date: 2020-07-21 -										
07/21/2020 14:08:07	0	0	276576875	38-56-005	Repair/Repla POWER SHAFT ASSEMB	07/21/2020 14:10:19	1DU298	O	DON	483.91
						WO Open Date: 2020-07-21			Count 1:	483.91
WO Open Date: 2020-08-17 -										
08/17/2020 15:44:18	0	0	276579488	38-66	Repair/Repla Mower Equipment	09/17/2020 11:30:00	1DU000	O	DON	952.09
08/17/2020 15:44:18	0	0	276579488	38-66-006	Repair/Repla Bearing/Pulley	09/17/2020 12:26:20	1DU000	O	DON	187.78
						WO Open Date: 2020-08-17			Count 2:	1,139.87
WO Open Date: 2021-08-23 -										
08/23/2021 00:00:00	0	0	276614132	56-66-001	Weld/Fabric Mower Deck	08/24/2021 00:00:00	1DU245	F	DON	345.65
						WO Open Date: 2021-08-23			Count 1:	345.65
WO Open Date: 2021-08-26 -										
08/26/2021 00:00:00	0	0	276614515	38-66-009	Repair/Repla Mower Blades	08/26/2021 00:00:00	1DU245	O	DON	103.70
08/26/2021 00:00:00	0	0	276614515	61-66-009	Travel Time Mower Blades	08/26/2021 00:00:00	1DU245	R	DON	69.13
						WO Open Date: 2021-08-26			Count 2:	172.83
WO Open Date: 2021-09-02 -										
09/02/2021 00:00:00	0	0	276615228	38-66-009	Repair/Repla Mower Blades	09/02/2021 00:00:00	1DU245	O	DON	276.52

Unit No: 201350 - 2001 DIAMOND DRF102C

WO Open Date: 2021-09-02 -

09/02/2021 00:00:00	0	0	276615228	61-66-009	Travel Time Mower Blades	09/02/2021 00:00:00	1DU245	F	DON	69.13

WO Open Date: 2021-09-02 Count 2: 345.65

Unit No: 201350 **Count: 51** **14,416.81**

Total Job Count and Repair Cost: **Count**: **51** **14,416.81**

Unit Job History

Report Title: UNITJOBHISTDISP - Unit Job History V17.0
Report Author: FleetFocus M5
File Path: C:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\T79I
Data Extracted: Thu Sep 23 2021 13:50:07 **Report User:** BORC1ERI
TZ: Central Standard Time
DLL Version: 2018.08.01
Report Comments: 5/31/06 - Focus No 7069 6/14/06 - Focus No 7996 & No 3053 7/12/06 - Focus No. 5392 03/28/07 - Focu 13916 07/02/07 - Focus No. 15696 10/08/07 - Focus No. 16414 02/08/08 - Focus No. 18696 01/21/09 - No. 22842 12/10/09 - Focus No. 24193 07/06/09 - Focus No. 25012 08/15/10 - Focus No. 31840 06/23/ Focus No 28649 09/06/11 - Focus No. 36445 11/11/11 - Focus No. 35887 06/04/12- Focus No. 39905 07/03/12 - Focus No. 39906 08/06/15 - FMV-3791
08/24/15 - FMV-3590 09/21/15 - FMV-4217 04/10/17 - FMV-9446

Parameters and Selection Filters

First Grouping: NONE
Second Grouping: OPEN_DT
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: {view_unit_wo.unit_no} = '201350' //Q=